

## PYROMETER USING STEPPER AND LED LIGHTING HARNESS WIRE IDENTIFICATION AND POSITION



(viewed from the wire IN side of the plug)

## **WIRING DIAGRAM**

- 1. Red to Probe
- 2. Yellow to Probe
- 3. X=Empty
- 4. White Dash Lights, or may be empty for non LED gauges

(viewed from the wire IN side of the plug)

