

VHX-1019

Dakota Digital Universal VHX Instrument Installation

Your new VHX-1019 kit includes:

VHX Display



Universal Sender Pack








CAT5 Cable

Control Box




Installation

1. Use the provided template to mark out the 6 ¾" diameter opening needed to fit the VHX display. Ensure adequate clearance behind desired mounting location; the display requires approximately 2" of depth.



2. With the appropriate opening cut, carefully place the VHX display from the front side and attach the four (4) L-brackets to the back of the display using the provided thumb nuts.



3. Remove the protective film, and then attach the provided CAT5 Cable to the back of the VHX display. Carefully route the other end to the control box mounting location and refer to the main manual for wiring instructions.





MARNING: This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov



4510 W. 61st St. North Sioux Falls, SD 57107 www.dakotadigital.com

Phone (605) 332-6513 Fax (605) 339-4106

dakotasupport@dakotadigital.com Copyright 2011 - Dakota Digital, Inc.