


WIRING DIAGRAM

1. Purple - Signal from sensor to gauge
2. Gray - 5 volt reference power
3. X=Empty
4. White - Dash lights or may be empty for non LED gauges.
5. X=Empty
6. Red - 12 volt switched power
7. Black - Ground to MAP sensor
8. Black - Gauge ground
9. X=Empty
10. X=Empty

(viewed from the wire IN side of the plug)



(viewed from the wire IN side of the plug)

