


VHX-1017

Dakota Digital Universal VHX Instrument Installation



## Installation


1. Use the provided template to mark out the opening needed to fit the VHX display. Ensure adequate clearance behind desired mounting location; the display requires approximately two inches of depth.



2. With the appropriate opening cut, remove the protective tape from the VHX display and attach the four (4) L-brackets to the back of the display using the provided thumb nuts.



3. Remove the protective film, then, attach the provided CAT5 cable to the back of the VHX display. Carefully route the other end to the control box mounting location and refer to the main manual for wiring instructions.





**AWARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to <a href="https://www.P65Warnings.ca.gov">www.P65Warnings.ca.gov</a>



4510 W. 61st St. North Sioux Falls, SD 57107 www.dakotadigital.com

Phone (605) 332-6513 Fax (605) 339-4106

dakotasupport@dakotadigital.com Copyright 2011 - Dakota Digital, Inc.